



Tandem 70 and Panasonic HPX300 Series Camera's

Anton/Bauer Main Number
203-929-1100

www.antonbauer.com

Anton/Bauer has identified a possible intermittent power issue with the Tandem 70 while powering a Panasonic HPX300/370 series camera. If you cycle camera power ON/OFF, the Tandem 70 may lock up causing you to lose power to the camera. Anton/Bauer does have a field upgradeable solution for it. This condition only happens if you do not have a battery installed on back of Tandem 70.

- Tandem 70's serial number 11937 thru 12595, and 13096 and higher can be field upgraded. The units in this range contain a socket software IC which can be easily changed.
- Older Titan 70 units and Tandem 70 units not in the above serial number range cannot be upgraded.
- If you have any questions or concerns please contact Customer Support Group.

If you have an older Titan 70 and would like to trade that unit in, contact the Anton/Bauer Customer Support Group.

Customer Support Group can be contacted in the following manner:

USA:
Email:
support@antonbauer.com
Phone: 203-925-4991 or
800-541-1667
Fax: 203-925-5203

EUROPE:
Email:
rploeg@antonbauer.com
Phone: +31-45-5639220
Fax: 203-925-5203

ASIA:
Email:
adamkoh@starhub.net.sg
Phone: +65-6285-7452

Latest Charger Revisions	
Model	Rev.
QUAD 2702	5.1
DUAL 2722	2.9
TWIN	18.0
Tandem 70	11.0
T2	2.9
TWQ	18.0
CINE VCLX Charger	3.0
Cine VCLX/2 Charger	1.0