

Compatibility Matrix | Gold Mount

antonbauer.com/chargercompatibility

Batteries

Chargers

Legacy products

	Dionic XT 90	Dionic XT 150	Titon 90	Titon 150	Titon 240	Titon SL 90	Titon SL 150	Titon Micro 45	Titon Micro 90	GO90	CINE 90	CINE 150	AB Digital G90	AB Digital G150	AB Digital G190	DIONIC 90	DIONIC HC	DIONIC HCX	Hytron 160	Hytron 50	Hytron 100	Hytron 140	DIONIC 26V 98***	DIONIC 26V 240	Titon Base****	
Anton/Bauer D2722 (Legacy)* Firmware: 3.6	✓	✓	✓	✓	✓	✓	✓	✓	✓	✗	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
Anton/Bauer Q2702(Legacy)* Firmware: 5.9	✓	✓	✓	✓	✓	✓	✓	✓	✓	✗	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
Anton/Bauer TM4 (Legacy)* Firmware: 11.0	✓	✓	✓	✓	✓	✓	✓	✓	✓	✗	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
Anton/Bauer TWIN (Legacy)* Firmware: 22.0	✓	✓	✓	✓	✓	✓	✓	✓	✓	✗	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
Anton/Bauer TWQ (Legacy)* Firmware: 22.0	✓	✓	✓	✓	✓	✓	✓	✓	✓	✗	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
Anton/Bauer T2 (Legacy)* Firmware: 3.6	✓	✓	✓	✓	✓	✓	✓	✓	✓	✗	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
Anton/Bauer Tandem 70 (Legacy) Firmware: 17	✓	✓	✓	✓	✓	✓	✓	✓	✓	✗	✓ ¹	✓ ¹	✓ ¹	✓ ¹	✓ ¹	✓	✓	✓	✓	✓	✓	✓	✓			
Anton/Bauer Tandem 150 (Legacy)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✗	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
Anton/Bauer LP2 Firmware: 6.0	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
Anton/Bauer LP4 Firmware: 4.0	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
Anton/Bauer Performance DUAL Firmware: 10	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
Anton/Bauer Performance QUAD Firmware: 10	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓			
Anton/Bauer (26V/PC+/PC)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
Anton/Bauer P-Tap Charger**	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓ ¹	✓ ¹	✓ ¹	✓ ¹	✗	✗	✗	✗	✗	✗	✗	✗			
Anton/Bauer GM2	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓ ¹	✓ ¹	✓ ¹	✓ ¹	✗	✗	✗	✗	✗	✗	✗	✗			
Anton/Bauer GM4	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓ ¹	✓ ¹	✓ ¹	✓ ¹	✗	✗	✗	✗	✗	✗	✗	✗			
Bebob S4 micro	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓ ¹	✓ ¹	✓ ¹	✓ ¹	✗	✗	✗	✗	✗	✗	✗	✗			
Bebob 2 Channel Micro AS2Micro	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓ ¹	✓ ¹	✓ ¹	✓ ¹	✓ ¹	✗	✗	✗	✗	✗	✗	✗	✗			

For charger firmware updates & to schedule repairs please contact your nearest service center: antonbauer.com/servicecenter
Charger must be using the up to latest firmware

Legend

✓	Tested, compatible	✗	Not compatible	~	Does not fully charge
✓ ¹	Tested, compatible but LCD shows 97%	-	Not tested	■	Incompatible mount type

* Charger may need a firmware upgrade - please contact antonbauer.com/servicecenter for more information.
 ** All the P-Tap Chargers are not compatible with these batteries: (HYTRON 50, 100, 140, Dionic 90, 160, HC and HCX), the batteries do not have a P-Tap port.
 *** DIONIC 26V Batteries have a specialised charger to manage the increased charging current.
 **** Titon Base charges via a P-tap charger which plugs into a wall socket.

Compatibility Matrix | Gold Mount

antonbauer.com/chargercompatibility

Batteries

Chargers

Chargers	Titan												Legacy products										DIONIC 26V					
	XT 90	XT 150	90	150	240	SL 90	SL 150	Micro 45	Micro 90	Micro 150	GO90	CINE 90	CINE 150	AB Digital G90	AB Digital G150	AB Digital G190	DIONIC 90	DIONIC HC	DIONIC HCX	Hytron 160	Hytron 50	Hytron 100	Hytron 140	26V 98	26V 240	Titon Base		
Bebob S1 Micro	√	√	√	√	√	√	√	√	√	√	-	√ ¹	√ ¹	√ ¹	√ ¹	√ ¹	X	X	X	X	X	X	X	X	-			
Bebob AS2	-	-	-	-	√	√	√	-	-	-	√	√ ¹	√ ¹	√ ¹	√ ¹	X	X	X	X	X	X	X	X	X				
BLUESHAPE D-Tap	√	√	√	√	√	√	√	√	√	√	√	√ ¹	√ ¹	√ ¹	√ ¹	√ ¹	X	X	X	X	X	X	X	X			X	
BLUESHAPE CGTR2P	√	√	√	√	√	√	√	√	√	√	√	√ ¹	√ ¹	√ ¹	√ ¹	√ ¹	X	X	X	X	X	X	X	X				
BLUESHAPE CGTRIM-45	√	√	√	√	√	√	√	√	√	√	√	√ ¹	√ ¹	√ ¹	√ ¹	√ ¹	X	X	X	X	X	X	X	X				
BLUESHAPE CGTRIM-60	√	√	√	√	√	√	√	√	√	√	√	√ ¹	√ ¹	√ ¹	√ ¹	√ ¹	X	X	X	X	X	X	X	X				
CORE P-Tap PB70CI5US	√	√	√	√	√	√	√	√	√	√	√	√ ¹	√ ¹	√ ¹	√ ¹	√ ¹	X	X	X	X	X	X	X	X			√	
CORE GPM-X2A	√	√	√	√	√	√	√	√	√	√	√	√ ¹	√ ¹	√ ¹	√ ¹	√ ¹	X	X	X	X	X	X	X	X				
CORE SWX X2A	√	√	√	√	√	√	√	√	√	√	√	√ ¹	√ ¹	√ ¹	√ ¹	√ ¹	X	X	X	X	X	X	X	X				
CORE FLEET Micro DM2	√	√	√	√	√	√	√	√	√	√	√	√ ¹	√ ¹	√ ¹	√ ¹	√ ¹	X	X	X	X	X	X	X	X				
CORE FLEET Micro QM4	√	√	√	√	√	√	√	√	√	√	√	√ ¹	√ ¹	√ ¹	√ ¹	√ ¹	X	X	X	X	X	X	X	X				
CORE FLEET Quantum	√	√	√	√	√	√	√	√	√	√	√	√ ¹	√ ¹	√ ¹	√ ¹	√ ¹	~	~	~	~	~	~	~	~				
CORE FLEET D2	√	√	√	√	√	√	√	√	√	√	√	√ ¹	√ ¹	√ ¹	√ ¹	√ ¹	X	X	X	X	X	X	X	X				
CORE FLEET Q4	√	√	√	√	√	√	√	√	√	√	√	√ ¹	√ ¹	√ ¹	√ ¹	√ ¹	X	X	X	X	X	X	X	X				
FXLion Single Position Charger PL-Q80A	√	√	√	√	√	√	√	√	√	√	√	√ ¹	√ ¹	√ ¹	√ ¹	√ ¹	X	X	X	X	X	X	X	X				
FXLion Mini 2 Channel Charger FX-M2A	√	√	√	√	√	√	√	√	√	√	√	√ ¹	√ ¹	√ ¹	√ ¹	√ ¹	X	X	X	X	X	X	X	X				
FXLion 2 Pos Charger PL-4680A	√	√	√	√	√	√	√	√	√	√	√	√ ¹	√ ¹	√ ¹	√ ¹	√ ¹	X	X	X	X	X	X	X	X				
IDX D-Tap VL-DT	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X			X
Frezzi FLC-2	√	√	√	√	√	√	√	√	√	√	√	√ ¹	√ ¹	√ ¹	√ ¹	√ ¹	X	X	X	X	X	X	X	X				
PAG PL16+	X	X	-	-	-	-	-	-	-	-	√	-	-	-	-	-	-	-	-	-	-	-	-	-				
SWIT Dual-Channel S-3812A	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X			
SWIT SC-304A	√	√	√	√	√	√	√	√	√	√	√	√ ¹	√ ¹	√ ¹	√ ¹	√ ¹	X	X	X	X	X	X	X	X				
Watson P-Tap C-SPT	√	√	√	√	√	√	√	√	√	√	√	√ ¹	√ ¹	√ ¹	√ ¹	√ ¹	X	X	X	X	X	X	X	X				
Watson Pro Quad	√	√	√	√	√	√	√	√	√	√	√	√ ¹	√ ¹	√ ¹	√ ¹	√ ¹	X	X	X	X	X	X	X	X				

For charger firmware updates & to schedule repairs please contact your nearest service center: antonbauer.com/servicecenter
Charger must be using the up to latest firmware

Legend

- √ Tested, compatible
- X Not compatible
- ~ Does not fully charge
- √¹ Tested, compatible but LCD shows 97%
- Not tested
- Incompatible mount type

* Charger may need a firmware upgrade
 - please contact antonbauer.com/servicecenter for more information.
 ** All the P-Tap Chargers are not compatible with these batteries:
 (HYTRON 50, 100, 140, Dionic 90, 160, HC and HCX), the batteries do not have a P-Tap port.
 *** DIONIC 26V Batteries have a specialised charger to manage the increased charging current.
 **** Titon Base charges via a P-tap charger which plugs into a wall socket.